(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

No previous record

## DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Set 2½"X30" Aluminum pipe with cap marked:

From which: 6" Pine bears N49°E, 17.6'


marked W1/16 S27 BT

5" Pine bears S66°E, 20.2'


marked **V1/16** S34 BT

9" Pine bears \$29°W, 11.7' location poster attached

Attached signs and painted a 6" red band around trees. A 1½" steel pipe bears N65°W, 1.85' (origin unknown).



SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)



Surveyor's Seal




I, Kevin A Todd
certify that the information shown herein is true and correct.

Signature of Ground Party Chief

Signature of Surveyor

DIAGRAM OF CORNER:

N. T31N R31W



= Corner recorded on the sheet

5619-S Registration Number

Office of Clerk and Recorder, County of Juncolu	
<b>*</b> i	February 1981, was noted on the cross-index plat and is
assigned page No. 997, in book No. /	Eleanor Llaughor by Michele Grow
	Cross Index No. V-14 T SIN R SIW Mer.
	Cross Index No. V T T SIV R SIVV Mer.