

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position
2. Description of evidence note discrepancies in the record state method of establishment or obliterated corners
3. Description of monument and accessories set to perpetuate the corner position
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana
6. Fill in Cross Index & Section Diagram at bottom of sheet.


CERTIFIED CORNER RECORDATION

Corner 4 HES 935 T. 31 N R. 32 W P.M.M. Lincoln County

ORIGINAL USDA NOTES: USDA - Forest Service 1919

CORNER: 2" Iron pipe, 36" long, 24" in ground with brass cap, marked 1919 4 HES 935
 "X" on 24" dia. Spruce tree, bears S.72°16'W., 33 lks distance
 "X" on 9" dia. Cedar tree, bears S.9°28'E., 38 lks distance
 Each blazed & scribed 4 HES 935 BT

EVIDENCE FOUND: 2" iron post with brass cap marked 1919 4 HES 935
 24" Aspen tree with "K" tag, S.72°W., 23.96 feet distance



CERTIFICATION

I, _____
 certify the information shown herein is true and correct.

Signature of Registered Professional Land Surveyor

I, Robert S. Roberts
 certify that this Corner Record correctly represents the work performed by me or under my direction in compliance with the "Corner Recordation Act" of 1922.

Signature of Registered Professional Land Surveyor

Date 11/30/82

Employer: Professional Surveyors, Inc.


SKETCH OF CORNER

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the January 21st day of 1982 was noted on the cross-index plat and is assigned page No. 1497, in book No. 1

Eleanor L. Vaughn by Betty L. Conces
 County Official deputy

Cross Index No. L, M-18, 19 T. 31N R. 32W P.M.M.

Sec. 14



• corner this sheet