INSTRUCTIONS

record used to evaluate the corner position and, note discrepancies in the record, state method of establish 2 Description of evidence corners
3. Description of monument and accessories set to perpetuate the corner position.

Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
 Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

Certification must be signed and sealed by Registered LarFill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

Corner	3	<u> </u>	<u>HES</u>	578	 Τ.	31	N	_R	32 W	_ P.M.M	Lincoln	 County

ORIGINAL G.L.O. NOTES: 1916


CORNER: Quartzite stone 24 x 10 x 7 inches, 14" in the ground, marked 3 HES 578 on S. face

11" Fir bears S.22°55'E., 10 lks 8" Fir bears N.26°30'W., 13 lks

Mound of stones, 4 ft. base, 2 ft. high, South of corner

EVIDENCE FOUND: Quartzite stone  $10 \times 10 \times 7$  inches, marked 3 HES 578 on South face and + on top

11" fallen dead tree bears S. 23°E., 6.6 feet, K-tag 8" rotten stump bears N.26°W., 8.6 feet, K-tag Mound of stone, 4 ft. base, .5 ft. high, South of corner



January 215t \_ day of 1984 record" was filed for record on the was noted on the cross-index plat and is assigned page No. 1504 L. Voughu by betty L. Conces
County Official Seputy book No. 仁 Cross Index No L, M-16 T. 31N R. 32W PMM · - corner this sheet