

CERTIFIED LAND CORNER RECORDATION
(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

None of original corner evidence was found. Corner was destroyed by construction of Lower Quartz Creek Road No. 601.

Found a balsam fir 14 ins. diam. bears S 44° 50'W - 85 lks. Dist., snag with scribing visible. (Record - A cross (X) on a balsam fir tree 7 ins. diam. bears S 44° 50'W - 85 lks. Dist., blazed and scribed 1 - H.E.S. 440, CC BT.)

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 10/28/70

For corner No. 1 and CC of H.E.S. 440.

SJS 2532 S

I set a 2 in. galvanized iron pipe 24 inches in the ground, with brass cap marked. I set corner from bearing and distance from original BT. from which:

1 & CC
HES

A lodgepole pine 17 ins. diam. bears N 89°W - 46 lks. dist., marked RM.

440

A spruce 9 ins. diam. bears N 7½°W - 58 lks. dist., marked RM.

1970

I placed an iron fence post with signs attached alongside the iron pipe.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.
(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

(Record from original field notes)

Surveyor's Seal

I, A. R. Trenkle
certify that the information shown herein is true and correct.

A. R. Trenkle

Signature of Ground Party Chief

I, Stanley J. Skousen
certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Stanley J. Skousen

Signature of Surveyor

2532 - S

Registration Number

DIAGRAM OF CORNER:

N. T31N R32W
1&CC
HES
440

= Corner recorded on the sheet

Office of Clerk and Recorder, County of Lincoln

This "corner record" was filed for record on the 20th day of April 1971, was noted on the cross-index plat and is assigned page No. 213, in book No. 1

ELEANOR L. VAUGHN, By: Mac Waters
County Official Deputy

Cross Index No. N-23 T. 31 R. 32 Mer.