INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- Description of monument and accessories set to perpetuate the corner position.
- topography ties, position of accessories, etc.
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana,
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

9 of HES 744 Lincoln Corner . County 1918 HES record by Harold Townsend: "Set a small stone, marked with a cross (x) under a quartzite stone, 26x10x5 ins. 16 ins. in the ground marked 9 HES 744 on SE face and a cross (X) on top. from which A cross (x) on a lodgepole pine tree, 5 ins. in dia., bears $N34^{\circ}21$ 'E, 42 links. distance. A cross (x) on a lodgepole pine tree, 5 ins. in dia., bears S41 13'E, 23 links distance each blazed and scribed 9 $\text{H.E.S.}\ 744\ \text{B.T.}$ Raise a mound of stone 4 ft. base, 2 ft. high, SE of corner.

II. Found a stone, 10x4 ins., 9 ins. above the ground, firmly set, marked X on top, 9 HES 744on the SE face, from which

> A dead pine, 12 ins. diam., bears S41 E, 15.2 ft. (23 lks.) dist., healed face. Mound of stone, SE, 2 ft. of corner.

III. Established two new bearing trees:


A fir, 10 ins. diam., bears N43 $^{\circ}$ E, 15.6 ft. dist., mrk. 9 HES 744 BT. A fir, 8 ins. diam., bears N34 $^{\circ}$ W, 33.2 ft. dist., mrk. 9 HES 744 BT.

Painted red bands around the bearing trees and attached Land Survey Monument and Bearing Tree signs.

Set a 6 ft. galvanized steel guard post with Land Survey Marker and Property Boundary decals, E. 3 ft.

Rebuild mound of stone SE of corner.

Magnetic declination: 20 East



CERTIFICATION

formation shown herein is true and correct

Signature Ground Party Chief

Lhomas M. Hommel

Ronald A. Pearson

certify that this Corner Record correctly represents work performed by me or under my disection in compliance with the "Corner lon in compliance et seq., M.C.A.)

12/9/92 Reg. No. 9008LS


U.S. FOREST SERVICE

SKETCH OF CORNER . This "corner

Office of Clerk and Recorder, County of 12-21-97 record" was filed for record on _ was noted on the cross-index plat and is assigned page No. book No. _

County Officia 9 HES 744

Cross Index No.



corner this sheet