
-CERTIFIED CORNER RECORDATION

Corner CE 1/16 Sec. 8 T. 31N R. 33W P.M., MT Lincoln County

XX-AMENDED-XX

I. 1994 Certified Corner Recordation, page no. 7300, by Alvah F. Hughes, 7322LS: Set by survey, a 3/4 in. diam. aluminum rod, 30 ins. long, 26 ins. in the ground, with a 3 1/4 in. diam. aluminum cap, mkd. as shown.



Established two bearing trees:

A larch, 9 ins. diam., bears East, 9.4 ft. dist., mkd. "CE 1/16 S8 BT". A fir, 9 ins. diam., bears N06°E, 13.6 ft. dist., mkd. "CE 1/16 S8 BT".


- II. Found a 3/4 in. diam. aluminum rod, with a 3 1/4 in. diam. aluminum cap mkd. as shown above and witnessed by the 1994 bearing trees.
- *Amended the 1994 Certified Corner Recordation, filed in the Lincoln County Courthouse, May 3, 1995, page no. 7300, due to errors found in the 1994 survey methods, I amended the corner as follows: I moved the found aluminum rod to the newly established position, as determined by survey. I reset the 30 ins. long, 3/4 in. diam. aluminum rod, 25 ins. in the ground, with the original 3 1/4 in. diam. aluminum cap, mkd. as shown.

I used existing bearing trees and established new bearings and distances:

A fir, 10 ins. diam., bears N17°E, 11.5 ft. dist., mkd. "CE 1/16 S8 BT". A larch, 10 ins. diam., bears S79°E, 11.95 ft. dist., mkd. "CE 1/16 S8 BT".

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East



G-08

31N