

-CERTIFIED CORNER RECORDATION

Corner SE 1/16 Sec. 8 T. 31N R. 33W P.M., MT Lincoln County

XX-AMENDED-XX

I. 1994 Certified Corner Recordation, page no. 7309, by Alvah F. Hughes, 7322LS: Set by survey, a 3/4 in. diam. aluminum rod, 30 ins. long, 28 ins. in the ground, with a 3 1/4 in. diam. aluminum cap, mkd. as shown.





Established two bearing trees:

A larch, 5 ins. diam., bears N72°W, 22.7 ft. dist., mkd. "SE 1/16 S8 BT". A pine, 5 ins. diam., bears N10°W, 8.0 ft. dist., mkd. "SE 1/16 S8 BT".

Set a 6 ft. steel galvanized guard post, West, 4.0 ft. dist., with Land Survey Monument and Bearing Tree signs attached.


- II. Found a 3/4 in. diam. aluminum rod, with a 3 1/4 in. diam. aluminum cap mkd. as shown above and witnessed by the 1994 bearing trees.
- III. *Amended the 1994 Certified Corner Recordation, filed in the Lincoln County Courthouse, May 3, 1995, page no. 7309, due to errors found in the 1994 survey methods, I amended the corner as follows: I moved the found aluminum rod to the newly established position, as determined by survey. I reset the 30 ins. long, 3/4 in. diam. aluminum rod, 26 ins. in the ground, I replaced the old cap with another 3 1/4 in. diam. aluminum cap, as during the move, the cap was destroyed, mkd. new cap as shown.

I used existing bearing trees and established new bearings and distances:

A pine, 6 ins. diam., bears N16°E, 5.8 ft. dist., mkd. "SE 1/16 S8 BT". A larch, 7 ins. diam., bears N79°W, 18.6 ft. dist., mkd. "SE 1/16 S8 BT".

Painted bearing trees and attached Land Survey Monument and Bearing Tree signs.

Magnetic Declination: 20° East



Cross Index

H-08

31N ^{R.} 33W

.M., MT