## INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 3. Description of monument and accessories set to perpetuate the corner position
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- Certification must be signed and search by Land
  Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION


Corner \_\_\_ E 1/4 of Sec. 8 T. 31 N., R. 33 W., P.M.M. Lincoln County

1893 G.L.O. original record by D. P. MUMBRUE: Set a quartzite stone, and 2 bearing trees.

1967 B.L.M. remonumentation record by J. E. FRENCH et al: The 1/4 corner of secs. 8 and 9, monumented with a loosely set quartzite stone, 20 x 10 x 6 ins., mkd. 1/4 on the W. face, and witnessed by the remains of the original bearing tree:

A pine stump, 20 ins. diam., bears S. 75 3/4 W., 29 lks. dist., mkd. 1/4 S.(record)

At the corner point, set an iron post, 30 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd. as shown:



from which new bearing trees:

A larch, 7 ins. diam., bears S. 87  $^{\circ}$  E., 44 lks. dist., mkd. 1/4 S9 BT. A fir, 7 ins. diam., bears S. 57 1/2  $^{\circ}$  W., 23 lks. dist., mkd. 1/4 S8 BT.

Bury the original stone alongside the iron post.

II. Found a 2 1/2 in. diam. iron pipe, pushed over by logging activity, with 3 1/2 in. B.L.M. brass cap mkd. as shown above, from which:

A pine stump, 16 ins. diam., bears  $876^{\circ}$ W, 19.1 ft. (28.9ks.) dist., "1/4" visible.

A larch, 10 ins. diam., bears  $887^{\circ}E$ , 15.7 ft. (23.7 lks) dist., healed face.

A fir, 10 ins. diam., bears \$57 W, 29.0 ft. (43.9 lks.) dist., healed face.

III. Straightened pipe to original position and verified by found bearing trees.

Painted a red band around bearing trees and attached Land Survey Monument and Bearing Tree signs.

No guard post set.

Magnetic Declination: 20° East.

