- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories.
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

## **CERTIFIED CORNER RECORDATION**

Corner: 1/4 Corner; Sec. 1&36 T.31N. R. 34W. P.M.M. Lincoln County 1/4 Corner; Sec. 36&1 T.32N. R. 34W.

1967 BLM Record: Set a 2-1/2 ins. iron pipe, 24 ins. in the ground, with brass cap from which:

A fir, 10 ins. dia., bears S18°W, 65 lks (42.9 ft.) A pine, 20 ins. dia., bears N78°W, 23 lks (15.2 ft.)

1983Record: (Hill, 5612S)

Found a 2-1/2 ins. BLM pipe, 4 ins. above ground, with brass cap from which:

A pine, 22 ins. dia., bears N77°W, 15.2 ft., with overgrown blaze. A fir, 15 ins. dia., bears S20°W, 43.0 ft., with visible scribing.

2010 Found:

We find a 3-1/4 ins. dia., BLM brass cap, marked as shown below from which:

A pine, 27 ins. dia., bears N77°W, 15.2 ft., with a chopped out heel blaze and no

visible scribing.

A fir, 16 ins. dia., bears S18°W, 43.0 ft., with an overgrown heel blaze.

2010 Perpetuation:

Bearing trees affixed with BT tags, LSM signs, snow blazed and painted red bands.

Steel spikes driven into BT's, side center at point of measurement.

We set a galvanized steel post West, 1.0 ft from monument, with LSM and USFS boundary decals.

S. STAN R34W

1/4 S36

1/4 S36

T31N R34W

DROASTRAL SURVEY CHARL

AND MANA CELEBRATE

OR OF THE INVENTED TO DISTURD TO DISTURDING TO DISTUR

CERTIFICATION

I, Travis R. Williams
certify the information shown herein is true and

Signature Ground Party Chief

Ken F lenking

I, Ken E Jenkins
certify that this Corner Record correctly
represents work performed by me or under my
direction in compliance with the "Corner Execution Act" (70-22-191, et seq.; M.CA.)

Signature of Surveyor & Seal

Date: 12/2010 Reg. No. 9330 LS

Employer: Montana Northwest Company

P.O. Box 8777, Missoula, MT 59807

406-721-4033 Project No.1617-10

**SKETCH OF CORNER** 

Office of Clerk and Recorder, County of	. This "corner
231783 BOOK:	CCR CCGR'S PAGE: 11752 Pages: 1
record" was filed for rec state of montana	LINCOLN COUNTY
was noted on the cross-i RECORDED: 03/30/2	2011 11:03 KOI: CCER'S
was noted on the cross-1 TAMMY D. LAUER (	CLERK AND RECORDER
book No. FEE: \$0.00	ELERK AND RECORDER  BY: Sense Sense Sept Service Septents  ST COMPANY P.O. BOX 8777, MISSOULA, MONTANA
TO: MONTANA HORTHWE	ST COMPANY P.O. BOX 8777, MISSOULA, MONTANA
	County Official

Sec. 1