

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories,
5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner: 1/4 Sec Corner, Secs 5 & 32 T. 31& 32N. R. 34W. P.M.M. Lincoln County

1903 GLO Record: Set fir post and established 2 bearing trees.

1982 Record: No evidence of fir post.
(Stabb 5619S) Found 1 in. dia. steel pipe witnessed by original bearing trees.
Set 32 ins. x 3-1/2 ins. dia. alum. pipe, 26 ins. in the ground. Raised a 3 ft. dia. collar of stone around the monument.

1998 Record: Found 2-1/2 ins. dia. alum. pipe, 4 ins. above the ground, with 3-1/4 ins. dia. alum. cap, (Boyer 9750LS) surrounded by 3 ft. dia. mound of stone.
Cedar snag, 22 ins. dia., bears S21°30'E, 7.6 ft., w/ visible scribe
Carsonite post, bears South, 1.0 ft. from the monument.

Established new bearing trees:
Hemlock, 8 ins. dia., bears S79°E, 45.7 ft., mkd "X BT"
Hemlock, 8 ins. dia., bears S16°W, 21.9 ft., mkd "1/4 S5 BT"
No trees available in Section 32

2010 Found: We find 3-1/4 ins. dia. alum. cap, marked as shown below, on a 2-1/2 ins. dia. alum. pipe, rising 0.3 ft. above the ground, surrounded by a mound of stone.
From which:
Hemlock, 9 ins. dia., bears S79°30'E, 45.9 ft., scribed "X" on snow blaze & "BT" on face blaze
Hemlock, 10 ins. dia., bears S16°W, 21.9 ft., scribed "1/4 S5 BT"
Cedar snag, 22 ins. dia., bears S21°30'E, 7.6 ft., face blaze chopped out, no visible scribing

2010 Perpetuation: We establish no new references monuments.
We set a galvanized steel post, East, 0.5 ft. from the monument with LSM and USFS boundary decals.

Bearing trees were affixed with BT tags and painted red band.

SKETCH OF CORNER

CERTIFICATION

I, Keith Brandt
certify the information shown herein is true and correct.
Keith Brandt
Signature Ground Party Chief

I, Ken E Jenkins
certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.S.A.).
Ken E Jenkins
Signature of Surveyor & Seal

Date: 10/2010 Reg. No. 9330 LS
Employer: Montana Northwest Company
PO Box 8777, Missoula, MT 59807
406-721-4033 Project No. 1617-10

Office of Clerk and Recorder 231791 BOOK: CCR CC&R'S PAGE: 11760 Pages: 1
 record" was filed for record STATE OF MONTANA LINCOLN COUNTY
 was noted on the cross-index RECORDED: 03/30/2011 11:11 KOI: CC&R'S
 book No. TAMMY D. LAUER CLERK AND RECORDER
 FEE: \$0.00 BY: *Tammy D. Lauer*
 TO: MONTANA NORTHWEST COMPANY P.O. BOX 8777, MISSOULA, MONTANA
 County Official

