

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories.
5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

Corner: Section Corner; Secs. 1,2,35,36 T. 31N. R. 34W. P.M.M. Lincoln County  
Section Corner; Secs. 35,36,1,2 T. 32N. R. 34W.

1902 GLO Record: Set a limestone, 20 ins. x 8 ins. x 6 ins., 15 ins. in the ground, for cor. of sections 1,2,35 and 36, marked with 1 notch in East and 5 notches on the West edges from which:  
 A Cedar, 10 ins. dia., bears N72°E, 54 lks (35.6 ft.), marked "T32NR34WS36BT".  
 A fir, 5 ins. dia., bears S70°30'E, 61 lks (40.3 ft.), marked "T31NR34WS1BT".  
 A fir, 16 ins. dia., bears S65°W, 40 lks (26.4 ft.), marked "T31NR34WS2BT".  
 A Tamarack, 24 ins. dia., bears N45°W, 18 lks (11.9 ft.), marked "T32NR34WS35BT".

1979 Record:  
 (Ninneman, 534S) COS No. 564 depicts a BLM brass cap for the section corner.

2010 Found: We find a 6 ins. x 6 ins. concrete block with a 3/4 ins. square metal bolt embedded in the center. The block is set firm and level with the ground from which:

A treated wood fence post bears West, 3 ft., with a location tag attached dated 4-25-64. Information on the tag places the section corner 3 ft. East.  
 A galvanized steel post with an LSM decal, bears South, 3 ft.

2010 Perpetuation: Establish new bearing trees as follows:

A Ponderosa pine, 19 ins. dia., bears N5°E, 43.7 ft., scribed "T32NR34WS36BT".  
 A fir, 13 ins. dia., bears N73°W, 13.1 ft., scribed "T32NR34WS35BT".

Bearing trees affixed with BT tags, LSM signs, snow blazed and painted red bands.

Steel spikes driven into BT's, side center at point of measurement.

We set a galvanized steel post West, 0.5 ft. from monument, with LSM and USFS boundary decals.

### SKETCH OF CORNER

#### CERTIFICATION

I, Travis Williams  
 certify the information shown herein is true and correct.

Travis Williams  
 Signature Ground Party Chief

I, Ken E Jenkins  
 certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the Montana Recordation Act" (70-22-101, et seq., M.C.A.)

Ken E Jenkins  
 Signature of Surveyor & Seal

Date: 12/2010 Reg. No. 9330 LS

Employer: Montana Northwest Company

P.O. Box 8777, Missoula, MT 59807

406-721-4033 Project No.1617-10

Sec. 2

Office of Clerk and Recorder, County of \_\_\_\_\_ This "corner  
 record" was filed for record (231792 BOOK: CCR CC&R'S PAGE: 11761 Pages: 1  
 was noted on the cross-index STATE OF MONTANA LINCOLN COUNTY  
 book No. \_\_\_\_\_ RECORDED: 03/30/2011 11:12 KOI: CC&R'S  
 TAMMY D. LAUER CLERK AND RECORDER  
 FEE: \$0.00 BY: Tammy D. Lauer  
 TO: MONTANA NORTHWEST COMPANY P.O. BOX 8777, MISSOULA, MONTANA

County Official

Cross Index No. A-21 T. 31N R. 34W PMM

● - Corner this sheet

