- Original and/or subsequent record used to evaluate the corner position.
- Description of evidence found, note discrepancies in the record, state method of establishing lost or obtterated
- urnent and accessories set to perpetunte the corner position.
- 4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- 6. Fill In Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

34W SW Corner Sec. 17 Lincoln Corner

1. 80.00 chains:

Set a limestone, 14 X 10 X 8 inches, 10 inches in the ground, for Corner of Sections 7,8,17, and 18, marked with 4 notches

on S. and 5 notches on E. edges; from which

A Cedar, 7 inches diameter, bears N.35010 E., 24 links distance,

marked T.31N.,R.34W. S.8B.T.

A Cedar, 12 inches diameter, bears S.65°30'E., 13 links distance,

marked T.31N., R.34W. S17B.T.

A Cedar, 10 inches diameter, bears S.46° 30'W., 11 links distance,

marked T31N.,R.34W S18B.T.

A Pine, 20 inches diameter, bears N.11030'W., 28 links distance,

marked t.31N., R.34W S7B.T.


2. Found B.L.M. standard brass cap marked as shown below from which,

A 20" Larch bears N.27°W 95 links.

A 20" Larch bears N.59°E 76 links. A 12" Fir bears S.43½°E 60 links.


A 10" Larch snag bears S64 3/4°W 41 links.

Painted monument and accessories with bright red paint.



book No. ..

Found B.L.M. standard brass cap marked as shown.



Eleanort Vaughnby Bette County Official

Cross Index No.

T. 31N R. 34W

· corner this sheet