

## INSTRUCTIONS

1. Original and subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

## CERTIFIED CORNER RECORDATION

$\frac{1}{4}$  Corner Common to Sections 3 & 10 T. 33N R. 26W P.M.M. Lincoln Count.

BLM & GLO Record: (GLO Record in parenthesis)

The  $\frac{1}{4}$  sec. cor. of secs. 3 and 10, monumented with a limestone 5x10x15 ins., firmly set and mkd.  $\frac{1}{4}$  on the N. face.

from which the remains of the original bearing trees:

A larch, 9 ins. diam., bears S. 52 $\frac{1}{2}$ ° E., 55 lks. dist., with no visible marks. (Record: S. 50° E., 55 lks. dist.)

A pine, 6 ins. diam., bears N. 34° W., 26 lks. dist., mkd.  $\frac{1}{4}$  S3 BT. (Record)

At the corner point

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$  ins. diam., 26 ins. in the ground, in concrete, with brass cap mkd.

T33N R26W

$\frac{1}{4}$  S3

$\frac{1}{4}$  S10

1960

from which


A larch, 8 ins. diam., bears S. 69 $\frac{1}{2}$ ° E., 74 lks. dist., mkd.  $\frac{1}{4}$  S10 BT.

A larch, 7 ins. diam., bears N. 6 $\frac{1}{2}$ ° W., 65 lks. dist., mkd.  $\frac{1}{4}$  S3 BT.

Bury the original stone alongside the iron post.

Raise a mound of stone, 3 ft. base, 2 ft. high, N. of the iron post.

See reverse side for evidence found



## SKETCH OF CORNER

## CERTIFICATION

I, \_\_\_\_\_  
certify the information shown herein is true and correct.

Signature Ground Party Chief

S. R. Smith

I, \_\_\_\_\_  
certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)

S. R. Smith

Signature of Surveyor & Seal

Date: 1/29/82 Reg. No. 47403

Employer: Smith Surveying Co.

Office of Clerk and Recorder, County of Lincoln This "corner record" was filed for record on the July 28<sup>th</sup> day of 1982 was noted on the cross-index plat and is assigned page No. 1708, in book No. \_\_\_\_\_

Eleanor L. Thayer by Patty L. Conner  
County Official Deputy

Cross Index No. E-15 T. 33N R. 26W P.M.M.

Sec. 3 & 10

	S	3 $\frac{1}{4}$
	S	10 $\frac{1}{4}$

in this sheet

Found: Broken base of BLM monument still firmly set in concrete. 9" Larch, face overgrown, bears  $NS^{\circ}W$  42.78'. All other evidence has been destroyed by logging.

New Monumentation: At the location mkd. by the broken base, I set a standard 2" diameter aluminum monument with 3" cap mkd. as shown on opposite side.  
9" pine scribed " $\frac{1}{4}$  S 10 BT" bears  $S 65^{\circ}E$  14.49'