

INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.
2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
3. Description of monument and accessories set to perpetuate the corner position.
4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner C-S $\frac{1}{16}$ Sec 15 T. 33N R. 26W P.M.M. Lincoln County

There is no previous record of this corner having been set.


Set a 2 in x 30 in. Aluminium Pipe with a $3\frac{1}{2}$ in diameter Aluminium cap stamped as shown and raised a collar of stone.

From which

A 10" Tam. bears $S19^{\circ}W$, 5.90 ft.

A 7" Tam. bears $N84^{\circ}E$, 21.95 ft.

Both are scribed "C-S $\frac{1}{16}$ BT"



SKETCH OF CORNER

CERTIFICATION

I, Thomas Van Slyke
certify the information shown herein is true and correct.

Thomas Van Slyke
Signature Ground Party Chief

I, S. R. SMITH
certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.)

S. R. Smith
Signature of Surveyor & Seal

Date: _____ Reg. No. 47405


Employer: SMITH SURVEYING CO.

Office of Clerk and Recorder, County of Lincoln. This "corner record" was filed for record on the July 28th day of 1982 was noted on the cross-index plat and is assigned page No. 1744, in book No. _____

Eleanor L. Vaughn by Betty L. Conces
County Official deputy

Cross Index No. M-15 T. 33N R. 26W PMM

Sec. 15



• - corner this sheet

Section 15 T33N R26W

Series of Bearings: Solar Observation near 1/4 9

(N89°45'E 2650.56'-610) (N89°45'E 2650.56'-610)

S89°54'06"E 2654.24' N89°59'46"E 2652.55' 81m
1326.28' 1326.28'

Reset from
broken 81m
Monument

N89°59'30"E 2649.92'
1324.96' 1324.96'

2645.29'

1323.65'

1323.65'

N89°59'14"E

5292.59'

(S89°59'E 2647.26'-610)

(S89°59'E 2647.26'-610)

N89°56'44"E 2646.16' S89°57'29"E 2648.64' 81m
1323.08' 1323.08'

S89°54'03"E

1317.14'

1317.14'

5284.30'

2650.10'

DKm Br. Cap

S89°53'33"E 2639.45'

1319.72'

S89°53'48"E 2650.81'

S89°53'04"E 2644.62'

1322.31'

S89°53'33"E 2651.53' 81m

(N89°55'E 2646.60'-610) Gross (N89°55'E 2646.60'-610)