
## INSTRUCTIONS



- Description of monument and accessories set to perpetuate the corner position.
   Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.
- Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
- 6. Fill in Cross Index & Seciton Diagram at bottom of sheet

## **CERTIFIED CORNER RECORDATION**

Corner Sections 7 & 18 on W Range T33 N R. 26 W P.M.M. LINCOLN \_County Line

RECORD: GLO 1903

Set a fir post 3' long, 4" sq. 24" in the ground, for corner of secs. 7, 12, 13, and 8, marked T33N S7 on NE, R26W S18 on SE, S13 on SW, and N27W S12 on NW face; with 2 notches on N and 4 notches on S edge; from which A spruce, 28" diam., bears N 35½ E 14 lks. dist., marked T33N R26W

S 18 BT.

A spruce, 26" diam. bears S 9° E, 39 1ks. dist. marked T33N R26W,

'S 18 BT.

A spruce, 24" diam., bears S  $59\frac{1}{4}^{\circ}$  W, 28 lks. dist., marked T33N, R27W, S 13 BT.

A hemlock 12" diam, bears N 57°W, 42 lks. dist, marked T33N, R27W, S 12 BT.

RECORD: GLOC1911 Subdivisions of T33N, R27W set closing corners , RECORD: BLM 1976

The corner of secs. 7 and 18, on the E bdy. of the Tp., monumented with the decayed remains of a wood post, and witnessed by the remains of a wood post, and witnessed by the remains of the original bearing trees:

bearing trees:
A spruce stump, 24" diam, bears S 59¼ W, 28 lks. dist., mkd. BT.
A hemlock stump, 12" diam., bears N 57 W, 42 lks. dist., marked BT.
At the corner point set an iron post 30" long, 2½" diam., 24" in the ground, with brass cap from which new bearing trees:
A fir 7" diam., bears N 65½ E, 94 lks. dist., mkd. T33N R26W S18 BT.
A spruce, 12" diam., bears S 57 E, 38 lks. dist., mkd. T33N R26W

S7 BT.

Place the decayed remains of the original wood post alongside and raise a flat mound of stone, 2' diam., around the iron post.

## FOUND:

 $3\frac{1}{4}$ " BLM Brass Cap on Steel Pipe in a mound of stone. 10" W Fir bears N65 E 62.3' scribing visible N R26W S7 BT. 14" Spruce bears S58 E 25.2' scribing pitched over.

## MAINTENANCE:

Set a 6' Steel Post 3' away from monument, cleared brush away from corner. Maintained B.T.'s with signs and paint.

