CERTIFIED LAND CORNER RECORDATION

(REFERENCE FSM 7153.53)


DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Monument found in good condition as recorded. BT's alive and in good condition @ record bearings and distances.

1960 BLM Record

From remains of original bearing trees; set an iron post, 30" long, 21/2" diam., 26" in ground with brass cap marked as shown.

From which: A 6" pine bears N434°E, 20 lks., mkd., T34N R26W S35 BT A 5" pine bears S474°E, 34 lks., mkd., T34N R26W S2 BT A 7" pine bears S88½°W, 34 lks., mkd., T34N R26W S3 BT A 12" larch bears N16¼±W, 73 lks., mkd., T34N R26W S34 BT



DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 1979

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Certificate of Survey No. 747

Surveyor's Seal



certify that the information shown herein is true and correct.

Signature of Ground Party Chief

Thomas C. Hill certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Signature of Surveyor

DIAGRAM OF CORNER:

N. T34N R26W

= Corner recorded on the sheet

5612-5 Registration Number

Office of Clerk and Recorder, County of Lineala)

This "corner record" was filed for record on the 311 day of March

was noted on the cross-index plat and is

assigned page No. 633 , in book No.

Cross Index No...