- INSTRUCTIONS

 1. Original and/or subsequent record used to evaluate the corner position.

 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED	CORNER	RECORDATION
-----------	--------	-------------

	CERTIFIED CORNER RECOR	TOATION .	٠,
Corr	ner #12, HES 353 T. 32N R. 27W	P.M.M. Lincoln County	
	1915 USFS Record: Set stone with mound of ea	arth and marked 2 BT's.	
	1961 BLM Remonumentation: Cor. No. 12 of H.I quartize stone, 26x12x10 ins., firmly set in 353 on the NE face and an X on the top. Frotrees:	n the ground and marked 12 HES	
	A pine, blown down, 6 ins. diam., bears 12 HES 353 BT. (Record).	, , ,	į
	A larch, 16 ins. diam., bears N65°W, 39 overgrown. (Record: N65½W, 38 lks. dist	lks. dist., with scribing	
	At the corner point	·	
	Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diamond in concrete, with brass cap marked T321 R271 S 9	N / COR 12	•
	from which:	1961	
	A pine, 8 ins. diam., bears $S39^{\frac{1}{2}}$ E, 32 1	ks. dist., mkd. COR 12 HES 353 BT	
	A larch, 5 ins. diam., bears N87°W, 49 1		
•	Bury the original stone alongside the ire	on post.	
	Raise a flat mound of stone, 3 ft. diam.	-	
II.	I found a BLM brass cap flush without ground which:	, marked as shown, and from	
	A 10 in. pine bears S39°E, 19.5 ft., scr	ibing visible (Blown down)	
	A 6 in. larch bears N88°W, 31.7 ft., scr.		
	A 18 in. larch bears N68°W, 25.4 ft., sc	_	
III.	I paint red bands around the BT's and paint signs 54-3 & 54-9 to each BT. I set USFS so 54-9 attached alongside the found monument.	the blazes and attach USFS teel post with decals 54-2 &	*
N			
l	10"Larch		
<u> </u>	HES #353 1-31.7'NOOW Cor.#12	· · · · · · · · · · · · · · · · · · ·	
1	A 2/7/1/0000 / Dar#/7	CERTIFICATION Dennis D. Findorff	
	1 Varib	certify the information shown herein is true and correct.	•
	To the state of th	Signature Ground Party Chief	
	for the state of t	I Robert E. Findorff certify that this Corner Record correctly represents work performed	1
	Wind R	by me on under my dipeother in compliance with the "Corner Recordation act" (70-2740), et seq., M.C.A.)	
	10"Pine	Signature of Surveyor & Sept / Date 8/13/85 Reg. No. 3976ES	
	, , , , , , , , , , , , , , , , , , ,	Employer: Self	
_	SKETCH OF CORNER (SEE ABOVE)	Sec.	,
Of	fice of Clerk and Recorder, County of Lincoln	This "corner	
re	cord" was filed for record on	5	
Wa	as noted on the cross-index plat and is assigned page No3	1161, in ,	
	ok No County Office	y Subdiff Lit	
			- 1

• - corner this sheet