INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

T. ______ R. _____ P.M.M. SE 1/16 Sec. 30 Lincoln Corner _County No previous record. No evidence of a monument on the ground (Evidence of old Forest Service signs and blazes in area). III. At the determined corner position by survey, set a 3/4 in. dia. aluminum rod, 30 ins. long 24 ins. in the ground with attached 3 1/4 in. dia. U.S.D.A. Forest Service aluminum cap, marked as shown: SE 1/16 S30 9008Ls

1990

Placed a 2 ft. dia. rock collar around monument.

from which

A Larch, 14 ins. dia., bears S $\overset{\circ}{4}$ W, 21.4 ft. dist., mkd. SE 1/16 S30 BT. A Larch, 10 ins. dia., bears S $\overset{\circ}{62}$ W, 42.5 ft. dist., mkd. SE 1/16 S30 BT.

Set a guard post, with "Survey Marker" and "Property Boundary" decals attached, 3 ft. W. from corner.

Painted a red band around each bearing tree and attached "Land Survey Monument" and "Bearing Tree" signs where needed.

Magnetic Declination: East, 19



CERTIFICATION Gary C. Crismon Pearson certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.G.A.) 10/30/90 Reg. No. _ 9008LS Employer: U.S. FOREST SERVICE **SKETCH OF CORNER** Sec. Office of Clerk and Recorder, County of record" was filed for record on was noted on the cross-index plat and is assigned page No. book No. -· corner this sheet Cross Index No.