CERTIFIED LAND CORNER RECORDATION

(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Record: Set a limestone lh"X10"X6", 9" in the ground. From which: 36" Tamarack bears N 60 20' E, 37 LKS.

22" Tamarack bears S 37 45' E, 69 lks. 12" Tamarack bears S 69 30' W, 86 1ks. bears N 43 20' W. 61 1ks.

Found:

#" iron pipe at corner location (origin unknown) From which:
48" Broken Tamarack bears N84%°E, 114.5' visible scribing (origin unknown)


22" Fir bears S21°W, 106.8' visible scribing (origin unknown) 24" Fir bears N66°W, 163.0' visible scribing (origin unknown)

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Set a $2\frac{1}{2}$ Aluminum pipe with cap marked: Raise a mound of stone around cap.

This position was verified by ties to the 4 adjacent 1/4 corners and by ties to the railroad tracks as found on a map located in the offices of Lawrence Sverdrup, Attorney at Law, Libby, Montana

Buried %" iron pipe alongside monument.



SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Certificate of Survey #754

assigned page No. 1022, in book No.

DIAGRAM OF CORNER: Surveyor's Seal certify that the information shown herein is true and N. T30N R30W Sec 5 correct. MIT NT ONTA Signature of Ground Party Chief **S**5 Sl STEPHEN D. Stephen D Staab STAAR certify that I have carefully performed or reviewed the 5619 S work done on the diagrammed corner as reported on this recordation form and approve the same. SURVEY = Corner recorded on the sheet Signature of Surveyor Registration Number

This "corner record" was filed for record on the 15 day of 198/, was noted on the cross-index plat and is

Cross Index No. 0/3 T 32N