
CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

No Original Record of corner establishment on file.

No Evidence of Corner found on ground.



DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the CN 1/16 corner of Section 25:

Date of work: June, 1981

Set an aluminum pipe, 30 ins. long, 2-1/2 ins. diam., 22 ins. in the ground, with 3-1/4 ins. diam. aluminum cap marked as illustrated, for the exact corner position. From which:

A 23" dia. Ponderosa Pine bears S.69°E., 35.6 feet dist., mkd. CN1/16 S25 BT.

A 12" dia. Ponderosa Pine bears S.36°W., 31.3 feet dist., mkd. CN1/16 S25 BT.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

(N'/16

5 26 | 5 25)

N 89° 41'03.8'' \(\) 2622.2374'

Surveyor's Seal

I, L. A. Dolezal

certify that the information shown herein is true and correct.

Signature of Ground Party Chief

I, Melvin D. Lauteren


certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this

recordation form and approve the same.

Signature of Surveyor

4232-S
Registration Number

DIAGRAM OF CORNER:
Section 25, TACK



- = Corner recorded on the sheet

CN 1/16 corner, Section 25, T32N, R29W, P.M.M.

Office of Clerk and Recorder, County of Linusha)
This "corner record" was filed for record on the 22 day of	Jene 1981, was noted on the cross-index plat and is
assigned page No. 1045, in book No	Eleanse L Vaufa, by Bethy Bell,
3 Form 125—7887	Cross Index No. 5-23 1981, was noted on the cross-index plat and is County Official R 29 Mer.