
## CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

No Original Record of corner establishment on file. No Evidence of Corner found on ground.



DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: June 1981

At the N 1/16 corner of Sections 25 & 26:

Set an aluminum pipe, 30 ins. long, 2-1/2 ins. diam., 22 ins. in the ground, with 3-1/4 ins. diam. aluminum cap marked as illustrated for the exact corner position. From which:


dia. Tamarack bears S.21°E., 105.5 feet dist., mkd. N1/16 S25 BT.

A 12" dia. Tamarack bears N.72°E., 115.2 feet dist., Mkd. N1/16 S25 BT.

These two B.T.s the best two available, both having burned, dead sides, but both living trees with scribing in green wood.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)



Surveyor's Seal


L. A. Dolezal certify that the information shown herein is true and Signature of Ground Party Chief

<u>Melvin D. Lauteren</u> I, Meivin D. Lauteren
certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

fauler Signature of Surveyor

2-5E54

DIAGRAM OF CORNER: Section 25, T32N N. R29W, PMM



= Corner recorded on the sheet

N 1/16 corner of Sections 25 & 26, T32N, R29W. P.M.M.

Registration Number

Office of Clerk and Recorder, County of	ela)
assigned page No. 1044a, in book No	Elunas L. Vaufa, Ly Beth, Bell,
3 Form 125—7887	Cross Index No. S-21  T. 32  R. 29  Mer.