
CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

No Original Record of corner establishment on file. No Evidence of Corner found on ground-



DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


At the Witness Corner to the N-S 1/44 corner of Sections 25 & 26:

Date of work: Junea 1981

Set an aluminum pipe, 30 ins. long, 2-1/2 ins. diam., 22 ins. in the ground, with 3-1/4 ins. diam. aluminum cap marked as illustrated, for the exact corner position. From which:

A 16" dia Ponderosa Pine bears N-61°W - 42.7 ft dist,mkd "X" breast high & BT.

A 6" dia. Douglas Fir bears N.23°E.1 35.8 ft.dist.,mkd. "X" breast high & BT.



Surveyor's Seal

I, L. A. Dolezal certify that the information shown herein is true and correct. J. C. Wolg Signature of Ground Party Chief Melvin D. Lauteren

certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Melv faules Signature of Surveyor

> Z-5E54 Registration Number

DIAGRAM OF CORNER: Section 25, T32N, N. R29W, PMM

 = Corner recorded on the sheet M.C. N-Z I/PA ot Sections 25 & 26, T32N, R29W, P.M.M.

Office of Clerk and Recorder, County of	م
dodd-	0
This "corner record" was filed for record on the 2 day of	19.8., was noted on the cross-index plat and is
assigned page No. 1248 in book No.	June 1981, was noted on the cross-index plat and is alexander of Daughan by Detty Dell, County Official
	County Official Deputy
3 Form 125—7887	Cross Index No. U-ZI T.32 R. 29 Mer.