CERTIFIED LAND CORNER RECORDATION


(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Found $2\frac{1}{2}$ " X 30" iron post 26" in the ground with cap marked. From which,

A fir 8" dia., bears $N4\frac{1}{2}^{O}E$, 32 lks. dist. marked $\frac{1}{4}S18$ BT.

A pine 12" dia., bears $$\rm S13^{O}W$, 39 lks. dist., marked ${}^{1}\rm LS19~BT$.



DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 1978


Corner in good condition as found. Placed steel fence posts with National Forest boundary and attention signs south and west of cap.

Refer to Certificate of Survey, subdivision of section 19 T32N R29W, as recorded in Lincoln County Courthouse, Libby, Montana.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

\$13 | \$18 | N89°31°54°W| 2068.39° | \$18 | \$89°42°49°W| 2640.71° | \$18 | \$17 | \$20 | \$19

Surveyor's Seal



I, Thomas C. Hill WN LS. 16209 certify that the information shown herein is true and correct.

Signature of Ground Party Chief

Stanley J. Skousen 2532-S

certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

tarly 1 - Shousen Signature of Surveyor ´ | | |

= Corner recorded on the sheet

DIAGRAM OF CORNER:

T32N R29W S19

2532**S**

Registration Number

Office of Clerk and Recorder, County of LINCOLN	
This "corner record" was filed for record on the 17th day of	December 1979, was noted on the cross-index plat and is
assigned page No. 592, in book No.	Eleanor L. Daugha, by Detty Deels County Official Deep Reputy
	Cross Index No.