CERTIFIED LAND CORNER RECORDATION


(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Found $2\frac{1}{2}\text{"}$ X 30"iron post 26" in the ground with cap marked. From which.

A cedar 10" dia., bears N250E, 10 lks. dist. marked $\frac{1}{2}$ S 19 BT.

A hemlock 16" dia., bears S26 $^{\rm O}$ W, 41 lks. dist. marked $\frac{1}{4}$ S 24 BT.



DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


Date of work: 1978

Corner in good condition as found. Placed steel fence post, with National Forest boundary and attention signs, next to cap.


Refer to Certificate of Survey, subdivision of section 19 T32N R29W, as recorded in Lincoln County Courthouse, Libby, Montana.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)



Surveyor's Seal



Thomas C. Hill WN LS. 16209

certify that the information shown herein is true and correct.


Signature of Ground Party Chief

Stanley J. Skousen 2532-S

certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Signiture of Surveyor
25325

DIAGRAM OF CORNER:



= Corner recorded on the sheet

Registration Number

Office of Clerk and Recorder, County of LINCODN

This "corner record" was filed for record on the 17th day of Alexander 1979, was noted on the cross-index plat and is assigned page No. 593, in book No.

County Official County Official County Official County Official Mer.