## CERTIFIED LAND CORNER RECORDATION

(REFERENCE FSM 7153.53)

## DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Found a  $2\frac{1}{2}$ " X 30" iron post 26" in the ground with cap marked. From which

A spruce 6" dia., bears  ${\rm S3^OE}$  , 33 lks. dist., marked T32N R29W S29 BT.

A fir 12" dia., bears  $S57\frac{1}{2}^{0}W$ , 11 lks. dist., marked T32N R29W S30 BT

A pine 16" dia., bears N51 $^{\rm O}$ 30'E, 47 lks., dist., marked T32N R29W S20 BT. A tamarack 18" dia., bears N51 $^{\rm O}$ 45'W, 45 lks., dist., marked T32N R29W S19 BT.

T32N R29W:

S19 | S20
S30 | S29


1976
HLM

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work:

Corner in good condition as found. Set steel fence posts, on property lines, with National Forest boundary signs and attention signs next to corner.

Refer to Certificate of Survey, subdivision of section 19 T32N R29W, as recorded in Lincoln County Courthouse, Libby, Montana.



This "corner record" was filed for record on the 1746 day of December 1977, was noted on the cross-index plat and

Cross Index No.

County Office

Office of Clerk and Recorder, County of ......

assigned page No. 575, in book No.