CERTIFIED LAND CORNER RECORDATION


(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Found a 2½" iron pipe with brass cap marked:

6" Larch, N 16%° E, 54 links 6" Balsam, S 34%° W, 82 links

6" Larch, N 52° W, 30 links 30" Cedar, S 46° E, 28 links



DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 1979....

Corner in good condition as found. Placed a fiberglass post next to corner with Forest Boundary and Attention signs attached.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)





I,Stephen D. Staab ... 5619 S..... certify that the information shown herein is true and correct.

> Ephen D Staa Signature of Ground Party Chief

Stanley J. Skousen

certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same

Signature of Surveyor

DIAGRAM OF CORNER:

N. T32N R29W

\$20 S21 **S28** \$29

= Corner recorded on the sheet

.....2532 S. Registration Number

Office of Clerk and Recorder, County of...... This "corner record" was filed for record on the 5 day of March 1980, was noted on the cross-index plat and is Eleanor L Voughn County Official assigned page No...., in book No..... Cross Index No. R - 9 T 32 N R 29 W Mer.