CERTIFIED CORNER RECORDATION

T. 32 North R. 30 West P.M.M. Lincoln Corner SE Cor. Section 8

Original survey - 1893 - James Keerl and Abram Jaqueth

80.00 chains - Set a limestone, 16X10X8 inches, 10 inches in the ground for the corner to Sections 8,9,16, and 17, with 4 notches on the south and east edges, from which:

A 14" tamarack bears N59 °15'E, 155 links (102.3'), mrkd. "T32N R30W S9 BT" bears S33° 30'E, 125 links (82.5'), marked "T32N R30W S16 BT" A 24" tamarack bears S28°30'W, 55 links (36.3'), mrkd. "T32N R30W S17 BT" N69°W, 104 links (68.64'), marked "T32N R30W S8 BT"

1940 – As part of the completion survey for the township this comer was re-established as the comer for Sections 8 and 17 only. The bearing trees to the east were obliterated and a brass cap on a 2" pipe was set to replace the original stone. The stone was set flush to the surface on the west side of the brass cap. The iron pipe and brass cap was set 28 inches in the ground.

FOUND:

Found the 1940 brass cap on a 1" rod leaning to the south, approximately 18" out of the ground, from which:


A 6' tall 34" dbh fir bears N66°W, 68.97 feet with healed blaze. A 34"larch bears N28° E, 36.0 feet, with healed blaze.


SET:

I placed a rock cairn around the monument and established one new bearing tree:

A 6" doug fir bears N14°W, 22.5', marked "T32N R30W S8 BT"

I place a 6 foot metal post with Land Survey Monument decal 1 foot north of the corner. I attached bearing tree tags to all of the bearing trees and painted the blazes and scribing with red tree paint.





SKETCH OF CORNER

Office of Clerk and Recorder, County of record" was filed for record on _//-5-04 was noted on the cross-index plat and is assigned page no. 1040book no. / County Official depart