INSTRUCTIONS

Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

Description of monument and accessories set to perpetuate the corner position.
 Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner <u>4 Cor. Sec. 8 & 17</u> T. <u>32N</u> R. <u>30W</u> P.M.M. <u>Lincoln</u>

Original GLO Notes: Set a limestone 14x8x6 in., 9" in the ground for \$\frac{1}{4}\$ Sec. Corner, mkd. \$\frac{1}{4}\$ on the N. Face from which(1916):

A pine 6" dia. bears \$360W 21 lks, mkd. \$\frac{1}{4}\$ \$17 BT.

A fir 20" dia. bears \$N520W 42 lks, mkd. \$\frac{1}{4}\$ \$8 BT.

(By: Mans H. Coffin, Jr., R. Fitzhugh Maclean and James R. Cumming.

Found original GLO corner stone firmly in place, a limestone(Sandstone) 14x8x6 in., mkd ½ on the N. face. Reset cor. w/ 3½" aluminum cap on a driveable mon. (USFS) and buried the corner stone alongside. Cap is 4" out of ground. Built a rock cairn 3' in dia around mon. and cleared area around cor. to 6' dia.

Accessories: Found BT a 21" fir N55 W 26.8', blaze healed over.

New BT a 9" fir S45 W 29.9' mkd. ½ S17 BT.

Trees painted and signed as per USFS Specs. Set sign post

Cap Mkd: near corner.

T32N R30W

Decl. assumed 20°E.

S8 S17 3976ES 1987

> T32N **R30W S8** S17 3976ES 1987

CERTIFICATION certify the information shown herein is true and correct. Signature Ground Party Chief Robert E. Findorff that this Corner Regord correc presents work performed Date: 9/12/87Reg. No. 3976 Employer: Self

SKETCH OF CORNER (SEE ABOVE)

SKETOTI OF COMPER (SEE 715 9 7 27	
Office of Clerk and Recorder, County of Lincoln . This	Sec. 8.T32N.R30W
record" was filed for record on	
was noted on the cross-index plat and is assigned page No. 3709	in
book No Jan't bt Sugel by Signification	Deputy

Cross Index No. <u>J7</u> <u>T. 32N R. 30W PMM</u>
Adopted July 1, 1981, Montana Board of Professional Engineers & Land Surveyors

· - corner this sheet