CERTIFIED LAND CORNER RECORDATION

(REFERENCE FSH 5681.65)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

Found original stone firmly set, 16x8x6 inches, 10 inches in ground with $\frac{1}{2}$ on West face. (record same) Found a 1 inch galvanized iron pipe firmly set alongside the original stone, with bass cap marked, from which: a 25 inch larch bears, N. $42\frac{1}{2}^{\circ}$ W., 86 links, scribing visible 32, the remaining portion of scribing overgrown (record 30 inch tamarack bears N. $42\frac{1}{2}^{\circ}$ W., 86 links). Tree destroyed by road construction (record 14 inch tamarack, S 87° E., 59 links).



DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 7/26/67...

Raised a collar of stone 2 foot base, 1 foot high around galvanized iron pipe and original corner stone, from which:

9 inch larch bears N. 16^{10}_{2} E., 17 links, scribed $\frac{1}{4}$ S 33 RM

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.

(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

(Record from original GLO notes.)

•					•
, .					·/•
Surveyor's Seal	I, A. R. Trend certify that the correct.	the information shown her	ein is true and	DIAGRAM N. ↑ ↑ 3	OF CORNER:
. ,	***************************************	ure of Ground Party (Chief	*	<i>/</i> 4
	certify that I hav	e carefully performed diagrammed corner as and approve the same.	or reviewed the		5 32 5 33

Office of Clerk and Recorder, County of Lincoln

This "corner record" was filed for record on the .5th day of October 19.67, was noted on the cross-index plat and is assigned page No. 79, in book No. 1

Eleanor L. Vaughn, By 2 my Water County Official

Cross Index No. Z=9, T. 32, R. 30, Mer.

Signature of Surveyor

2532 5
Registration Number