INSTRUCTIONS

sequent record used to evaluate the corner position

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

- corners.

 3. Description of monument and accessories set to perpetuate the corner position.

 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ites, position of accessories, etc.

 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner NE 116, 5.9 T. 32N R. 3/W P.M.M. LINCOLN County

- 1) NO ORIGINAL EUIDENCE / RECORD
- 2) NONE
- 3) SET 31/2" ALUMINUM CAP ON 3/4" ALUM. ROD. FROM WHICH:

A 10" DBH. WHITE FIRST BEARS SOUTH 31.2FT (B.T.)
NEY16 59 BT

A "II" DEH. CEDAR SEARS SGS E 19.3FT (B.T.) BLAZE HEAD HIGH (OLD) NEYIG ST BT

SCRIBES AND 6" BANDS DAINTED RED.

STEEL POSTS BEAR, NEW ! 4 FT AND SWLY 1.1 FT.

BT TAGS AND SURVEY MONUMENT SIGNS ATTACHED TO BEARING TREES.

ROCK MOUND

	CERTIFICATION
NEY16 59 + 49745 1985 10"WHITE PINE 11"CEDAK	Signature Ground Party Chief Signature Ground Party Chief ERALD E. BUNTON certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the Corner Recordation Activity 22-101 by an M.C. Signature of Surveyor & Seal Date: 129/KS Reg. No. 4974 S Employer: BUNTON'S TECH. SVS., TNC.
SKETCH OF CORNER	Employer: 247070705 / SES : SVS 1
Office of Clerk and Recorder, County of Lincoln record' was filed for record on Sept 10, 1985	This "corner Sec. 9
was noted on the cross-index plat and is assigned page No3	070 in L
was noted on the cross-index plat and is assigned page 110.	11 6 1 1 1 1 1
book No Great BF Sugal Country Off	by Dill Dully
	aciai