

CERTIFIED LAND CORNER RECORDATION





(Reference FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)


Brass cap on edge of private drive marked:

14" Larch, S 20%° W, 55 links 12" Larch, N 741/2° W, 36 links

14" Larch, N 87° E, 52 links 56 links

14" Pine, S 49°E, 14" Larch, N 72° W,

51 links



DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 5/79

Corner in good condition as found. Placed a fiberglass post with Attention and National Forest Boundary signs attached, next to corner.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

Corner lies on edge of private drive approx. 400' East of junction of Noisy Creek Road and private drive.

See Certificate of Survey No. 755

MTA STEPHEN D. **STAAB** 5619 S SURVEYONE

Surveyor's Seal

DIAGRAM OF CORNER: Don Hardgrove certify that the information shown herein is true and N. T32N R31W correct. Signature of Ground Party Chief **S15** I, Stephen D. Staab certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this

recordation form and approve the same. Signature of Surveyor

= Corner recorded on the sheet

5619S Registration Number

This "corner record" was filed for record on the 5th day of March

assigned page No. 120 in book No.

... 19.*80*... was noted on the cross-index plat and is

County Official

Cross Index No. J-17 T 32N