DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)


NONE

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: 1979

Set an aluminum pipe (2½") with cap, 22" in ground marked:

8" Fir, S 43° E, 15.2', scribed N 1/16, S14, BT. 10" Fir, N 50° W, 35.0', scribed N 1/16, S15, BT.



SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

See Certificate of Survey No. <u>755</u>

Surveyor's Seal



I, Don Hardgrove certify that the information shown herein is true and correct.


Signature of Ground Party Chief

I, Stephen D. Staab certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.

Stephen D Stand
Signature of Surveyor

DIAGRAM OF CORNER:

N. T32N R31W



Section 14 = Corner recorded on the sheet

5619S Registration Number

Office of Clerk and Recorder, County of Sincela

This "corner record" was filed for record on the 5th day of March, 1980, was noted on the cross-index plat and is assigned page No. 126, in book No.

Cross Index No. K-17 T 32 N R 31 W Mer.