equent record used to evaluate the corner

Description of evidence found, not discrepancies in the record, state met

Description of monument and accessories set to perpetuate the corner position.

- Sketch of corner, show all pertinent data which can best be shown in a sketch exar ple, corner marking, topography ties, position of accessories, etc.
- st be signed and scaled by Land Sur rveyor registered in the State of Montana.
- Fill in Cross Index & Section Diagram at bottom of sheet.

1967

CERTIFIED CORNER RECORDATION

Corner of Sections 26,27,34,& 35 T. 32 N., R. 34 W., P.M.M. Lincoln County RECORD:

1903 GLO Original record by A.B. Benedict: Set a limestone and four bearing trees.

1968 BLM Remonumentation Record by W.E. Damm et. al: The corner of sections 26, 27, 34, and 35, monumented with a limestone, 18"x12"x5", firmly set, illegibly marked and witnessed by the remains of the original bearing trees.

At the corner point, set an iron post, 30" long, 25" diameter, 24" in the ground, with brass cap marked:

T32N R34W 527 526 \$35

From which:

The original bearing trees:

A Tamarack stump, 24" diameter, bears S56°E, 37 links distant, marked T32N R34W S35 BT. (Record: S60°E, 37 links)

À Fir stump, 15" diameter, bears N764°W, 51 links distant, marked T32N R34W S27 BT. (Record)

The new bearing trees:
A Pine, 8" diameter, bears N14½°E, 83 links distant, marked T32N R34W S26 BT.

A Fir, 9" diameter, bears S33°E, 49 links distant, marked T32N R34W S35 BT. A Pine, 10" diameter, bears S38½°W, 44 links distant, marked T32N R34W S34 BT. A Pine, 10" diameter, bears N59°W, 53 links distant, marked T32N R34W S27 BT.

FOUND:

Found $3rac{1}{4}$ " diameter BLM brass cap, marked as shown above, set in concrete at base of steel corner fence post. From which:

The original Tamarack stump position falls in a private access road (Record S60°E, 37 links).

A Fir stump, 15" diameter, bears N68°W, 33.66' distant, marked T32N R34W S27 BT. (Record: N76½°W, 51 links)
A Pine, 12" diameter, bears N14°E, 54.3' distant, marked T32N R34W S26 BT. (Record: N14½°E, 83 links) BT tag and location poster by KED 4975S 10/15/93.

A Fir, 9" diameter, now fallen and rotting, visible scribed face, moved southerly out of position.

A Pine, 14" diameter, bears S38°W, 28.9' distant, marked T32N R34W S34 BT. (Record: S38½°W, 44 links) BT tag and ATTENTION sign by KED 4975S 10/15/93.

A Pine, 14" diameter, blown over easterly from record position onto face with orange paint (Root wad generally fits Record: N59°W, 53 links)

PERPETUATION:

Established two new bearing trees:
A Pine, 13" diameter, bears S 9°E, 29.9' distant, marked T32N R34W S35 BT.
Land Survey Monument sign already on tree.
A Fir, 8" diameter, bears N66°W, 56.9' distant, marked T32N R34W S27 BT.

Painted red bands around the two new bearing trees and attached Bearing Tree signs to them.

8" FIR COT 14" PINE S 12" PINE	CERTIFICATION
15" FIR ON TO WAR THE STUMP OF	1, Kevin Todd to certify the information shown herein is true and correct. Signature Ground Party Chief
PRIVATE ACCESS ROAD	Signature Ground Party Chief 1. James R. Staples certify that this corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.C.A.) STAPLES
FENCE PINE STUMP FENCE PINE STUMP FALLEN 9" FIR W/ SKETCH OF CORNER SCRIBED FACE ROTTING	Date: 1-27-00 Reg. No. 9958 Employer: J.R.S. Surveying, Inc.
2 2 0	Sec. 27
record" was filed for record on	2000 age No. 10437
book No Count	y official
Cross Index NoV17 T32N F	R. 34W PMM