

CERTIFIED LAND CORNER RECORDATION

CENTER OF SEC. 18 TWP. 32 N., R. 34 W., M.P.M. (not established by original survey)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

1/4 Cor. Between Sec. 18 and Sec. 19 Twp. 32 N., R. 34 W., M.P.M.  
Squared post from which a 5" Fir bears S 14° E 15 lks. marked 1/4 S 19 B.T. 6" Fir  
N 41° W 9 lks. Marked 1/4 S 18 B.T. Original Corner and Bearing Trees destroyed  
by logging operation.  
We replaced with brass cap 2640 Feet West of Sec. Cor. common to Secs. 17, 18, 19, and 20  
Twp. 32 N., R. 34 W., M.P.M. and on straight line between said Sec. Cor. and Sec. Cor.  
common to Sec. 18 and 19 Twp. 32 N., R. 34 W., M.P.M. and Sec. 13 and 24 Twp. 32 N.,  
R. 35 W., M.P.M.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED  
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: July 1968

SEE OTHER SIDE

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY.  
(MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

SEE OTHER SIDE

Surveyor's Seal


I, J. H. Ninneman  
certify that the information shown herein is true and  
correct.

*J. H. Ninneman*  
Signature of Ground Party Chief

I, J. W. Ninneman 534 E.S.  
certify that I have carefully performed or reviewed the  
work done on the diagrammed corner as reported on this  
recording form and approve the same.

*J. W. Ninneman*  
Signature of Surveyor 534 E.S.

DIAGRAM OF CORNER:



○ = Corner recorded on the sheet  
Twp. 32 N., R. 34 W.

Registration Number

Office of Clerk and Recorder, County of Lincoln

This "corner record" was filed for record on the 24th. day of September 19. 68, was noted on the cross-index plat and is

assigned page No. 115, in book No. 1

10:05 A.M.  
ELEANOR L. VAUGHN  
County Official

1. Found two bearing trees.
2. We set a standard brass cap monument Marked and posted 14" Larch N 35°W-28.8 Feet  
Marked  $\frac{1}{4}$  with chain saw 12" Larch S 28° 30' E 32.7 Feet Marked  $\frac{1}{4}$  with chain saw.
3. Found stone and four bearing trees.
4. Found stone and two bearing trees subsequently replaced by brass cap by B.L.M.
5. Found stone and 1 Bearing tree Posted same.
6. Set standard brass cap at intersection of north-south and east-west centerline from  
which a 12" Pine bears N 72°W 24.4 feet marked center with chain saw. Posted  
10" Pine S 9°30'W 34.0 feet. marked center with chain saw. Posted.
7. Found stone scribed  $\frac{1}{4}$  bearing trees not evident. We marked and posted 12" Cedar  
S 70°45' W - 18 ft. marked  $\frac{1}{4}$  with saw 12" Cedar S 79°E 6 Ft. Marked  $\frac{1}{4}$  with chain saw.

Sec. 18 Twp. 32 N., R. 34 W., M.P.M.

