INSTRUCTIONS

- Original and/or subsequent record used to evaluate the corner position.

 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated
- 4. Sketch or corner, show all pertinent dat topography ties, position of accessories, etc.
- Certification must be signed and sealed by Registered Land Surveyor in State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

W & Section 27 32N. R. 3LW. County Corner,

Original G.L.O. Notes 1903 Allen B. Benedict

Set a granite stone, 18x12x8 ins., 12 ins. in the ground, for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on W. face; from which A fir, 8 ins. diam. bears N.41 E. 10 lks. dist. marked 1-4 S27 BT. A fir, 5 ins. diam. bears S.44 W. 12 lks. dist. marked 1-4 S28 BT.

II. I found the original stone scribed \(\frac{1}{4} \) with a X on top. The stone was lying loosely in a hole under a 30" tamarack long butt. Replaced stone. Found no bearing trees.

III. Davis Surveying Inc. 1987

I set 34" Aluminum Cap on a 5/8" diam. x 4" long rebar with the original stone alongside. Cap is stamped:

DAVIS 4975 S

CERTIFICATION

A 12" tamarack bears S.80°W. 7.5 feet from the center of tree.

\$ S28 BT. Notched at root crown.

An 8" tamarack bears S.5°W. 9.3 feet from the center of tree. Scribed 幸 S27 BT.

Painted a red band around BTs. Placed a St. Regis location posters on front of BTs.

Davis certify the info certify tha ents work performed

SKETCH OF CORNER	4/1914	ATIR		
of cala	Sec.	27		
Office of Clerk and Recorder, County of Lincoln. This "corner".				,
record" was filed for record on the January 29 day of 1987		+	- - 	
			ŀ	
was noted on the cross-index plat and is assigned page No. 3500, in	/ T	1-1		1
book No funt St Diegel by Del Distiff	<u> </u> -			
County Official Daput				

corner this sheet