(REFERENCE FSM 7153.53)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

FOUND:

None.

RECORD: No previous record.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: NOV. 1975___

We set 1 1/2" I.D. x 30" Forest Service Brass-Capped Pipe 24" in ground. Stamped as per sketch. We built a mount of stones around pipe and painted it red.

We make reference monuments for reference to corner. Description of reference monuments 1 and 2 as per sketch.

Steel Fence post with land survey monuments and location posters located as per sketch.

SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS/IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)






DIAGRAM OF CORNER:


Surveyor's Seal

I, Cartify that the information shown herein is true and correct.

Signature of Ground Party Chief

certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same \(\)

Signature of Surveyor



● = Corner recorded on the sheet 5.74_T52N_R54W_R.W.U.U. C-E-E-T. 1/64

Registration Number

Office of Clerk and Recorder, County of	130 p. m.
This "corner record" was filed for record on the day of	Manch 19.76, was noted on the cross-index plat and is
assigned page No. 434 in book No.	Eleamon J. Usughin by dherry Davis County Official depute
	Cross Index No. P-24-25 T 32 N -R-34 W Mer.