INSTRUCTIONS

- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner: Center 1/4 Section 24

T. 32N. R. 34W. P.M.M. Lincoln County

1975 Record:

No previous record.

(Shaw 2343S)

Set a 1-1/2 ins. dia. x 30 ins. Forest Service Brass Cap, 20 ins. in the ground, in a mound

of stones. From which:

Grand Fir, 8 ins. dia., bears S11°E, 13.8 ft., scribed RM1 Douglas Fir, 8 ins. dia., bears N87°W, 6.16 ft., scribed RM2

2010 Found:

We find a 2-1/2 ins. dia. brass cap, marked as shown below, on 2 ins. dia. steel pipe,

rising 0.65 ft. above the ground. From which:

Stump, 12 ins. dia., 1.4 ft., high, bears S11°E, 13.75 ft., w/ overgrown blaze

Douglas Fir, 12 ins. dia., bears N86°30'W, 6.0 ft., w/ healed blaze

2010 Perpetuation:


We establish new reference monument as follows:

Grand Fir, 10 ins. dia., bears N70°30'E, 35.5 ft., scribed "C1/4 S24 BT".

We set galvanized steel posts, North, 0.5 ft. and East, 3.1 ft. from the monument

w/ LSM and USFS boundary decals.

Bearing trees were affixed with BT tags, snow blazed, and a painted red band.



	Sec. 24	
Office of Clerk and Recorder, County of This "co	orner	1
record" was filed for record on STATE OF MONTANA LINCOLN COUNTY	ou rages: 1	
RECORDED: 03/30/2011 11:30 KOI: CCER'S		
was noted on the cross-index pl TAMMY D. LAUER CLERK AND RECORDER		
book No.	an april	1
TO: MOSTABA BORTHWEST COMPANY P.O. BOX 8777, MISS	SOULA, MOSTANA	l

County Official