- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

3. Description of monument and accessories set to perpetuate the corner position.

- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories,
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner: C-1/4 Corner; Sec. 14 T.32N. R. 34W. P.M.M. Lincoln County

1976 Record:

(Shaw, 2343S)

Set a 1-1/2 ins. x 30 ins. brass capped pipe, 24 ins. in the ground, from which:

A Douglas fir, 14 ins. dia., bears S26°E, 14.4 ft., scribed "RM1" A Cottonwood, 10 ins. dia., bears S81°W, 39.7 ft., scribed "RM2"

2010 Found:

We find a 2-1/2 ins. dia. brass cap on 1-1/2 ins. dia. metal pipe set firm, marked as shown below from which:

A fir stump, 20 ins. dia., bears S26°E, 24.5 ft., with visible scribing in a partially overgrown heel blaze.

2010 Perpetuation:


Establish new bearing trees as follows:

A Cottonwood, 18 ins. dia., bears S84°W, 45.1 ft., scribed "C1/4 S14 RM2" A Cedar, 15 ins. dia., bears N9°W, 35.2 ft., scribed "C1/4 S14 RM1"

Bearing trees affixed with BT tags, LSM signs, snow blazed and painted red bands.

Metal spike driven into BT's side center at point of measurement.

Set a galvanized steel post set S47°W, 0.3 ft from the monument with LSM and USFS boundary decals.



Office of Clerk and Recorder	, County of This "corner	Sec. 14
record" was filed for record	231831 BOOK: CCR CCER'S PAGE: 11800 Pages: 1 STATE OF MONTANA LINCOLN COUNTY	
was noted on the cross-inde	RECORDED: 03/30/2011 11:49 KOI: CCER'S	- • -
book No.	TEE: \$0.00 BY AND BECOMEN OF STATE OF S	
	County Official	

Sec. 14