INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

3. Description of monument and accessories set to perpetuate the corner position.

- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories,
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner: 1/4 Section Corner; Secs 16, 21 T. 32N. R. 34W. P.M.M. Lincoln County

GLO Record:

Set limestone and established 2 bearing trees.

1967 BLM Record:

Found original stone, firmly set and the remains of the SE bearing tree.

Set 30 ins. x 2-1/2 ins. dia. iron post, 24 ins. in the ground, w/ brass cap. Set original stone alongside.

From which:

Original BT is fir stump, 14 ins. dia., bears S52°E, 20 lks (13.2 ft.), mkd "1/4 21 BT"

Larch, 8 ins. dia., bears N52°30'E, 38 lks (25.1 ft.), mkd "1/4 S16 BT" Pine, 7 ins. dia., bears S42°30'W, 14 lks (9.2 ft.), mkd "1/4 S21 BT"

1982 Record:

Found 2-1/2 ins. dia. BLM brass cap, 6 ins. out of the ground.

(Hill 5612 S)

From which:

Larch, 11 ins. dia., bears N52°E, 25.1 ft., w/ visible scribing

Ponderosa Pine, 10 ins. dia., bears S41°30'W, 9.3 ft., w/ visible scribing

1995 Record: (Hughes 7322LS)

2-1/2 ins. dia. iron pipe, 4 ins. above the ground, firmly set, w/ 3-1/4 ins. dia. BLM brass cap.

From which:

Rotten remains of fir, bears S52°E, 13.0 ft.

Larch, 12 ins. dia., bears N52°E, 25.0 ft., w/healed face Pine, 13 ins. dia., bears S42°W, 9.2 ft., w/healed face

2010 Found:

We find a 3-1/4 ins. dia. brass cap on 2-1/2 ins. dia. steel pipe, marked as shown below, rising 0.4 ft. out of

ground. From which:


Larch, 13 ins. dia., bears N53°30'E, 24.8 ft., w/overgrown blaze & BT tag Ponderosa Pine, 18 ins. dia., bears S41°W, 9.3 ft., w/overgrown blaze & BT tag

2010 Perpetuation:

We establish no new reference monuments.

We set a galvanized steel post, West, 0.8 ft. from the monument w/ LSM and USFS boundary decals.

Bearing trees were affixed with BT tags and a painted red band.



SKETCH OF CORNER

CERTIFICATION

l, <u>Keith Brandt</u>
certify the information shown herein is true and correct.

Signature Ground Party Chief

, Ken E Jenkins

represents work performed by me or under my direction in compliance with the "Corner - Recordation Act" (70-22-101, et seq., M.C.A.)

Signature of Surveyor & Seal

Date: 9/2010 Reg. No. 9330 LS

Employer: Montana Northwest Company

PO Box 8777, Missoula, MT 59807

406-721-4033 Project No. 1617-10

TO: MOHTABA HORTHWEST COMPANY P.O. BOX 8777, MISSOULA, MOHTABA

County Official