INSTRUCTIONS

1. Original and/or subsequent record used to evaluate the corner position.

- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories,
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner: NW SW 1/64 Corner, Section 12 T. 32N. R. 34W. P.M.M. Lincoln County

1982 Record: (Hill 5612S)

No previous record of monumentation on file. No evidence found on the ground.

At the determined corner position, set a 1/2 ins. dia. x 24 ins. alum. rod, w/ alum. cap, 22 ins. in the ground, w/ a collar of stones.

From which:

Lodge Pole Pine, 6 ins. diam., bears S64°W, 18.3 ft., scribed "X BT" Larch, 6 ins. diam., bears S76°E, 6.6 ft., scribed "1/64 S12 BT"

2010 Found:

We find a 3-1/4 ins. dia. alum. cap, marked as shown below, on alum. rod, rising 0.3 ft. above the ground.

From which:

Lodge Pole Pine, 8-1/2 ins. diam., bears S64°W, 18.3 ft., w/ illegible scribing

& BT tag

Larch, 9-1/2 ins. diam., bears S76°E, 6.6 ft., w/ overgrown blaze & BT tag


2010 Perpetuation:

We establish no new reference monuments.

We set a galvanized steel post, North, 0.55 ft. from the monument w/ LSM, USFS and

property boundary decals.

Bearing trees were affixed with BT tags, and a painted red band.



Office of Clerk and Recorder, (County of	This "corner		$\overline{}$	
	231887 BOOK: CCR CC4R'	S PAGE: 11830 Pa		 -	
record" was filed for record on	P#COPD#D: 03/31/2011 10:05				
was noted on the cross-index p.	TAMMY D. LAUER CLERK AND R	ECORDER - /a			
book No	FEE: \$0.00 BY: To: MONTANA HORTHWEST COMPANY	P.O. BOX 8777, MISSOULA,	HOHTAHA		
	County Officia				