1. Original and/or subsequent record used to evaluate the corner position.

2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.

3. Description of monument and accessories set to perpetuate the corner position.

- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories,
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner: Section Corner; Secs. 35,36,1,2

T 32N

R. 34W. P.M.M. Lincoln County

Section Corner; Secs. 1,2,35,36

T.31N. R. 34W.

1902 GLO Record:

Set a limestone, 20 ins. x 8 ins. x 6 ins., 15 ins. in the ground, for cor. of sections 1,2,35 and 36, marked with 1 notch in East and 5 notches on the West edges from which:

A Cedar, 10 ins. dia., bears N72°E, 54 lks (35.6 ft.), marked "T32NR34WS36BT".

A fir, 5 ins. dia., bears S70°30'E, 61 lks (40.3 ft.), marked "T31NR34WS1BT".

A fir, 16 ins. dia., bears S65°W, 40 lks (26.4 ft.), marked "T31NR34WS2BT"

A fir, 16 ins. dia., bears S65°W, 40 lks (26.4 ft.), marked "T31NR34WS2BT". A Tamarack, 24 ins. dia., bears N45°W, 18 lks (11.9 ft.), marked "T32NR34WS35BT".

1979 Record:

(Ninneman, 534S)

COS No. 564 depicts a BLM brass cap for the section corner.

2010 Found:

We find a 6 ins. x 6 ins. concrete block with a 3/4 ins. square metal bolt embedded in the center. The block is set firm and level with the ground from which:

A treated wood fence post bears West, 3 ft., with a location tag attached dated 4-25-64. Information on the tag places the section corner 3 ft. East. A galvanized steel post with an LSM decal, bears South, 3 ft.

2010 Perpetuation:

Establish new bearing trees as follows:

A Ponderosa pine, 19 ins. dia., bears N5°E, 43.7 ft., scribed "T32NR34WS36BT". A fir, 13 ins. dia., bears N73°W, 13.1 ft., scribed "T32NR34WS35BT".

Bearing trees affixed with BT tags, LSM signs, snow blazed and painted red bands.

Steel spikes driven into BT's, side center at point of measurement.

We set a galvanized steel post West, 0.5 ft. from monument, with LSM and USFS boundary decals.

	CERTIFICATION I, Travis Williams certify the information shown herein is true and correct. Signature Ground Party Chief
	I, Ken E Jenkins certify that this Corner Record Corner II represents work performed by the or inder my the direction in compliance with the Corner II Recordation Act" (70-22-101; et al.) (M.G.A.)
	Signature of Surveyor & Seal
·	Date: 12/2010 Reg. No. 9330 LS
	Employer: Montana Northwest Company
	P.O. Box 8777, Missoula, MT 59807
	406-721-4033 Project No.1617-10
SKETCH OF CORNER	

Office of Clerk and Recorde	r. County of	This "corner	
	· · · · · · · · · · · · · · · · · · ·	11853 Pages: 1	
record" was filed for record	STATE OF MONTANA LINCOLN COUNTY		
was noted on the cross-index	RECORDED: 03/31/2011 10:28 KOI: CCER'	9 ,	
		0-01	
book No.	FEE: \$0.00 BY:	Deani Spuly	
•	TO: MOSTANA SORTHWEST COMPANY P.O. BOX 8777,	MISSOULA, MONTANA	
	County Official	 	

Sec. 35