

- 1. Original and/or subsequent record used to evaluate the corner position.
- 2. Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated corners.
- 3. Description of monument and accessories set to perpetuate the corner position.
- 4. Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of
- 5. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.
- 6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner: Secs 30, 31,25&36

T. <u>32N.</u> R. <u>34 & 35W.</u> P.M.M.

<u>Lincoln</u> County

1903 GLO Record:

Set limestone and established 4 witness trees

1967 Record:

Found a granite stone & 2 bearing trees.

(Damm)

Set brass cap on iron post. Established 3 bearing trees. Buried original stone alongside monument.

1988 Record:

Found BLM brass cap, 3-1/4 ins. dia., on a 2-1/2 ins. dia. iron pipe, 8 ins. out of the ground.

(Hill 5612S)

Cedar, 13 ins. dia., bears N32°E, 53 lks (35 ft.), w/ visible scribing Stump, 6 ft. high, bears S24°E, 7 lks (4.6 ft.), w/ visible scribing Snag, bears S32°W, 23 1/2 lks (15.5 ft.), w/ visible scribing

Cedar, 8 ins. dia., bears N54°W, 77 lks (50.8 ft.), w/ visible scribing Fallen tree, bears N35°W, 37 lks (24.4 ft.), w/ visible scribing

Established new reference monuments as follows:

Fir, 5 ins. dia., bears S20°E, 19 lks (12.5 ft.), mkd "T32N R34W S31 BT" Cedar, 5 ins. dia., bears S52°W, 7 lks (4.6 ft.), mkd "T32N R35W S36 BT"

2010 Found:

We find a 3-1/4 ins. dia. brass cap on 2-1/2 ins. dia. steel pipe, marked as shown below, rising 0.7 ft. from

the ground. From which:

From which:

Cedar, 12 ins. dia., bears N32°30'E, 34.7 ft., w/ visible scribing "S30 BT" & BT tag

Douglas Fir, 9 ins. dia., bears S21°E, 12.5 ft., w/ healed face blaze & BT tag

Cedar, 9 ins. dia., bears S56°W (Record S52°W), 4.6 ft., scribed "T32N R35W S36 BT"

Cedar, 12 ins. dia., bears N53°W, 50.2 ft., w/ overgrown blaze & LSM tag

2010 Perpetuation:

We establish no new reference monuments.

We set a galvanized steel post, North, 1.3 ft. from the monument w/ LSM and USFS boundary decals.

Bearing trees were affixed with BT tags and a painted red band.



CERTIFICATION

I, Keith Brandt certify the information shown herein is true and

correct.

ent Signature Ground Party Chief

I, Ken E Jenkins ONT44
certify that this Corner Reconficorrectly, represents work performed by me or inder my direction in compliance with the Corfet! Recordation Act" (70-22-10]; et seq. M.C.A.) 9.5

Signature of Surveyor & Seal //

Date: 12/2010 Reg. No. <u>9330 L</u>

Employer: Montana Northwest Company

PO Box 8777, Missoula, MT 59807

406-721-4033 Project No. 1617-10

SKETCH OF CORNER

Office of Clerk and Recorder,	County of	This "corner		
record" was filed for record c	231917 BOOK: CCR CCER'S STATE OF MONTANA LINCOLN COUNTY	PAGE: 11860 Pages: 1		
was noted on the cross-index	RECORDED: 03/31/2011 10:35 KOI:	CCGR'S		
book No.				

Sec. 36					