INSTRUCTIONS

Original and/or subsequent record used to evaluate the corner position.
 Description of evidence found, note discrepancies in the record, state method of establishing lost or obliterated

corners.

3. Description of monument and accessories set to perpetuate the corner position.

4. Sketch or corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc.

5. Certification must be signed and sealed by Registered Land Surveyor in State of Montana.

6. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

T. 32N R. 34W P.M.M. Lincoln County 1/4 S11 S12 i. Corner .

B.L.M. record 1967: From found original evidence: Set a 2½"x30" iron post 24" in ground. I. From which: A 6" fir bears S79°W., 8 1ks. (new)
A 15" pine bears S30°15'E., 19 1ks.

Found an iron pipe 9" above ground with B.L.M. brass II. cap mrk. as shown:

From which: A 9" fir bears S82°W., 5.7 ft. Healed face. A 17" pine bears S23°E., 11.9 ft.

Scribing visible.

Painted red bands around bearing trees.

.basse



	THOMAS C. HILL 5612 S SURVE
582° W 511 512 1967 BLM SKETCH OF CORNER 37" AAS12 BT	CERTIFICATION I. Anthony J. Bachman certify the information shown herein is true and correct. Control Significant Ground Party Chief Thomas C. Hill I. Certify that this Corner Record correctly represents work performed by me or under by direction in compliance with the "Corner Recordation Act" (70-22-101, et seq., M.D.A.) Signature of Surveyor & Seal Date P. S. Reg. No. 56/25 Employer: U.S.F.S.
Office of Clerk and Recorder, County of Lincoln record" was filed for record on the Gug 9th was noted on the cross-index plat and is assigned page No. 183 book No	,

511/512 31/4 Brass 11"OBH Oouslas For Ponderosa Pine NUS

