CERTIFIED CORNER REC	CORDATION
Corner N 1/16 S20 S21 T 33 N. R. 31	W. P.M.M. Lincoln County
I. <u>Record:</u> None	
II. Found: No record monuments found.	· ·
III. <u>Perpetuation:</u> At the corner point, determined by steel rebar 30 ins. long, 29 ins. in the cap marked as shown below from the cap marked as shown belo	ground, with a 3 1/4 ins. diam.
A Douglas fir 17 ins. diam., bears S79°E, 4.25 ft. dist., scribed N 1/16 S21 BT.	
A Douglas fir, 13 ins. diam., bears N40°W, 14.7	70 ft. dist., scribed N 1/16 S20 BT.
Painted faces and 6 in. wide red bands to all Survey Monument and Bearing Tree signs.	bearing trees and attached Land
	•
Magnetic declination: 18° East	
Equipment used: Hand compass and loggers to	ре
NOTE: Refer to Certificate of Survey No. 4168 Lincoln survey information.  Kootenai Surveyors Inc., 314 California Av., Libby, MT.	59923 (406) 293-4354 CERTIFICATION
13" fir  14.25 ft. 17" fir	Employer: Kootenai Surveyors Inc.
SKETCH OF CORNER	
Office of Clerk and Recorder, County of Lincoln This "c  record" was filed for record on	Sec. 21  Sec. 21  Sec. 21  Sec. 21  Sec. 21  Sec. 21  Sec. 21

Sign .