CERTIFIED LAND CORNER RECORDATION

(REFERENCE FSH 5681.65)

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (IF KNOWN)

No evidence of original corner found. Area in heavy burn.

Corner position established by proportionate methods. See plat of Pipe Creek Properties for section subdivision.

DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

Date of work: Nov. 1973

Set $1\frac{1}{2}$ " I.D. x 30" galvanized iron pipe 18 inches into ground, stamped as shown below, from which a 12 inch Lodgepole Pine scribed RM bears North 38 West 5.4 feet distance; a 10 inch Lodgepole Pine bears North 69 East 29.4 feet distance.


SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNERS IF DETERMINED IN THIS SURVEY. (MAY SKETCH OR PASTE REPRODUCTION ON REVERSE SIDE.)

Surveyor's Seal	ī	DIAGRAM
	certify that the information shown herein is true and correct.	N. (737)
	Signature of Ground Party Chief	28
	I, J. T. Shaw	
	certify that I have carefully performed or reviewed the work done on the diagrammed corner as reported on this recordation form and approve the same.	= Corner recor

2343-S Registration Number

Cross Index No. T. 13 T. 33 N R. 31 W P.Mer.

DIAGRAM OF CORNER:



= Corner recorded on the sheet

Office of Clerk and Recorder, County of Linesh.

This "corner record" was filed for record on the find day of Leasing 1974, was noted on the cross-index plat and is assigned page No. 328, in book No.

Eleanor L. Vaugh, Mac. Watson, Lyfuly County Official

