

CERTIFIED CORNER RECORDATION

Corner C-W 1/16 S25 T. 33 N., R. 34 W., P.M.M. Lincoln County

Record :

None.

Found Evidence :

None.

Perpetuation :

From a section breakdown by Davis Surveying, Inc., on record at the Lincoln County Courthouse, Libby, Montana, at the computed position set a 5/8 inch diam. by 24 inch long steel rebar, 22 inches in the ground, with a 1 1/4 inch diam. yellow P.V.C. cap marked KED 4975-S, from which:

A Douglas Fir, 7 1/2 ins. diam., bears N 29° W, 9.90 feet dist., scribed (C-W 1/16 S25 BT).


A Western Tamarack, 9 ins. diam., bears S 65° W, 8.50 feet dist., scribed (C-W 1/16 S25 BT).

Painted 6 inch wide bands and scribed faces red.

Attached Bearing Tree signs to both trees.



Magnetic Declination: 18° East



Sketch of Corner

CERTIFICATION

I, John Damon

certify the information shown herein is true and correct

John Damon
Signature of Ground Party Chief

I, Kenneth E. Davis

certify that this Corner Record correctly represents work performed by me or under my direction in compliance with the "Corner Recoration Act" (70-22-101, et seq., M.C.A.)

Kenneth E. Davis
Signature of Surveyor & Seal

Date: _____ Reg. No. 4975-S

Employer: Davis Surveying, Inc.


Office of Clerk and Recorder, County of Lincoln

This "corner record" was filed for record on 1-20-99

was noted on the cross-index plat and is assigned page No. 10284

in book No. Carol M. Cumming By RB
County Official

Section



Cross Index No. C-W 1/16 S25 T. 33 N., R. 34 W., PMM

• THIS CORNER