
## INSTRUCTIONS

and used to evaluate the corner position.



Description of monument and accessories set to perpetuate the corner position.

Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topography ties, position of accessories, etc. Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

Fill in Cross Index & Section Diagram at bottom of sheet.


## CERTIFIED CORNER RECORDATION

Corner C-S-S-SE1/256 Sec 17 T. 33N R. 34W P.M.M. Lincoln \_ County

1) No records found at Lincoln County Courthouse

No evidence found on the ground


At the corner position as determined by survey, set a 5/8"x 30" rebar, with a  $3\frac{1}{2}$ " 31 aluminum cap, marked as shown:



From which:

A 16" Douglas Fir bears S51°W, 10.9' distant, scribed CSS SE1/256 S17 BT. A 14" Larch bears N38°W, 9.7' distant, scribed CSS SE1/256 S17 BT.

Monument was set 0.1' above grade. A 6' steel post with Land Survey monument and Forest Service Property Boundary decals attached was placed 0.8' east of monument. Blazes and scribing on bearing trees were painted red. Bearing tree tags and Land Survey monument signs were attached to trees.



ρ - η	SE⅓ Se	c. 17	
Office of Clerk and Recorder, County of Mcoh. This "corner			ļ
record was filed for record on			
was noted on the cross-index plat and is assigned page Noin		_	
book No. 10317 County Official County Official			
country official /		+	

Cross Index No. <u>M.75-8</u> T. <u>33</u> R. <u>34</u> PMM