
INSTRUCTIONS

equent record used to evaluate the corner position



Description of evacence forms, not discrepances in unfactors, see the description of monument and accessories set to perpetuate the corner position.

Sketch of corner, show all pertinent data which can best be shown in a sketch exam

Certification must be signed and sealed by Land Surveyor registered in the State of Montana.

Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION


R. 34W P.M.M. Lincoln County Corner C-S-SE1/64 COR SEC 17 T. 33N

No records found at Lincoln County Courthouse 1)

No evidence found on the ground 2)

At the corner position as determined by survey, set a $5/8"\times~30"$ rebar, with a $3\frac{1}{4}"$

aluminum cap, marked as shown:




From which:

An 11" Larch bears N30°E, 37.3' distant, scribed C S SE1/64 S17 BT. A 14" Larch bears N67°E, 32.0' distant, scribed C S SE1/64 S17 BT.

Monument was set flush with ground 9' easterly of easterly edge of Highway 2. A 5" wood post with Land Survey Monument, Forest Service Property Boundary, and Location signs attached was placed 2.2' south of monument. Blazes and scribing on bearing trees were painted red. Bearing tree tags and Land Survey Monument signs were attached to trees. A fence corner bears N42°E, 13.5'.

CERTIFICATION "" LARCH JAMES R. **STAPLES** 9958 LS PRIVATE USFS *5-3-99* Reg. No. SURVE SKETCH OF CORNER J.R.S. Surveying, Inc.

Office of Clerk and Recorder, County of This "corner record" was filed for record on assigned was noted on the cross-index plat and 10319 book No.



T. 33N R. 34W _ PMM Cross Index No. M.5-8