INSTRUCTIONS

Description of evidence found, not discrepancies in the record, state method of establishing lost or obliterated corners

Description of monument and accessories set to perpetuate the corner position.


Sketch of corner, show all pertinent data which can best be shown in a sketch example.

Certification must be signed and scaled by Land Surveyor registered in the State of Montana. Fill in Cross Index & Section Diagram at bottom of sheet.

CERTIFIED CORNER RECORDATION

Corner SMC-east line Gov't Lot 5 T. 33N R. 34W P.M.M. Lincoln


- No records found at Lincoln County Courthouse. 11
- No evidence found on the ground. 2)
- The position as determined by survey for the W-W-W1/256 corner was found to be below the Ordinary High water mark of the Kootenai River- at a point 20' north of the computed position on the east line of Government Lot 5, safely above the High Bank, set a 5/8" x 31 30" rebar, with a 34" aluminum cap, marked as shown:



From which:

A 15" Douglas Fir, bears N36°E, 29.0' distant and scribed S17 SMC BT. A 12" Douglas Fir, bears N 6°W, 27.5' distant and scribed S17 SMC BT.

Blazes and scribing on bearing trees were painted red. Bearing tree tags and Land Survey Monument signs were attached to trees. A 6' steel post with Land Survey Monument and Forest Service Property Boundary decals attached was placed 1' south of monument.



ρ' Λ	SW4 S	Sec.	17	
office of Clerk and Recorder, County of JMCNO. This "corner record" was filed for record on				
was noted on the cross-index plat and is assigned page Noin book Noini				
County Official /				

T. 33N R. 34W PMM Cross Index No. N-5.25