## INSTRUCTIONS

Original and/or subsequent record used to evaluate the corner position.

Description of evidence found, not discrepancies in the record, state method of establishing lost or obliterated composition of monument and accessories set to perpetuate the corner position.

Sketch of corner, show all pertinent data which can best be shown in a sketch example, corner marking, topographic methods are all pertinent and accessories and the state of the sample of the state of the sample of the state of the sample o

ple, comer marking, topography ties, position of accessories, etc.

Certification must be signed and sealed by Land Surveyor registered in the State of Montana.


## CERTIFIED CORNER RECORDATION

\_\_P.M.M.\_\_\_\_County T. 33N \_\_ R.<u>34W</u> Corner C-S-SW1/64 Cor Sec 17

No records found at Lincoln County Courthouse 1)

No evidence found on the ground 2)


At the corner position as determined by survey, set a 5/8"x 30" rebar, with a  $3\frac{1}{4}$ " aluminum cap, marked as shown: 3)



From which:

A 5" Douglas Fir, bears N10°W, 20.2' distant and scribed C S SW1/64 S17 BT. An 11" Douglas Fir, bears N67°W, 31.7' distant and scribed C S SW1/64 S17 BT.

Blazes and scribing on trees were painted red. Bearing tree tags and Land Survey Monument signs were attached to trees. A 6' steel post with Land Survey Monument and Forest Service Property Boundary decals attached was placed 2' north of monument.



$\rho \sim \rho$	SW% Sec 17			
Office of Clerk and Recorder, County of Jacoba. This "corner record" was filed for record on		-		
was noted on the cross-index plat and is assigned page Noin				
book No. 10322 Old M. Umming Super Scounty Official		_	,	

Cross Index No. <u>M.5-6</u> T. <u>33N</u> R. <u>34W</u>